


Generic Sample WORK BREAKDOWN STRUCTURE



- 4410 Make the Items
 - 4411 cut bar stock
 - 4412 weld fabrication
 - 4413 machine faces
 - 4414 assemble components
- 4450 Routine Tests
- 4480 Acceptance Tests